



NOTE :
 Induction Welding Disc can be used to secure Hydro-Prufe Membrane in place. Fasten Induction Disc through Hydro-Ultra Mat G12 as necessary to secure Membrane in place.



DETAIL NAME:
**TYPICAL PLANTER
 TERMINATION DETAIL (OPT # 1)**

Scale:	Date:	Drawing #:
NTS	12-01-15	HP-PL-002