



NOTE :
 Induction Welding Disc can be used to secure
 Hydro-Prufe Membrane in place. Fasten
 Induction Disc through Hydro-Ultra Mat G12
 as necessary to secure Membrane in place.



DETAIL NAME:
**TYPICAL PLANTER
 TERMINATION DETAIL (OPT # 2)**

Scale:	Date:	Drawing #:
NTS	12-01-15	HP-PL-003