



NOTE : Induction Welding Disc can be used to secure Hydro-Prufe Membrane in place. Fasten Induction Disc through Hydro-Ultra Mat as necessary to secure Membrane in place.



DETAIL NAME:

**TYPICAL PLANTER
TERMINATION DETAIL (OPT # 1)**

JOB NAME:

Scale:

NTS

Date:

12-01-14

Drawing #:

HP-PL-002